

## Case Study: Ablution Block Barricade



“The signs are good that this is a future product for all our open abluition blocks.”

– Client

The glass blockades in an abluition block had been vandalised. Mesh netting was used to replace it, but it attracted nesting sparrows and proved difficult to clean and maintain.

The council sought our FRP mini mesh grating to replace it and provide a superior, long-term solution.

Our mini mesh is visually appealing, low maintenance, and virtually unbreakable.



Connect with the team: ☎ 0800 464 377 🌐 [frp-products.co.nz](http://frp-products.co.nz)

