

CASE STUDY: Walkway Upgrade



Challenge

A local council faced challenges with a muddy public walkway path that became a slip hazard for pedestrians.

Solution

Our FRP regular mesh grating was placed and secured directly onto the soil, resulting in minimal infrastructure costs. FRP grating is durable, non-slip, corrosion-resistant, and provides natural drainage.

Outcome

Installing our FRP regular mesh grating transformed the walkway path, making it durable, long-lasting, and safer for pedestrians. The council was pleased with the improved usability and environmental benefits, ensuring the community can enjoy the path for years.